

INDIAN RAILWAY SIGNAL ENGINEERING MANUAL PART II
(2001 EDITION)

Addendum and Corrigendum Slip No.2

Chapter XII, Para 12.192 & Chapter XIX, Para 19.148

Replace the existing para 7.1 of annexure 7 to para 12.192 & para 4.1 of annexure 30 to para 19.148 of the SEM Pt.II, 2001 edition with the following:-

para 7.1 of annexure 7 to para 12.192

"Cleaning and lubricating of moving parts. Point chairs in which signalling and interlocking gears are connected (generally upto third sleeper from toe of the switch) shall be cleaned regularly by signal staff. Also check other point chairs are cleaned regularly by Permanent way staff."

para 4.1 of annexure 30 to para 19.148

"Check the machines are kept free from rust, dirt and fixtures. Check for tightness. Point chairs in which signalling and interlocking gears are connected (generally upto third sleeper from toe of the switch) shall be cleaned regularly by signal staff."

Case No.2006/SIG/G/4
New Delhi, dated 19.04.2007

BY ORDER



(Mahabir Prasad) 14/07
Addl. Member(Signal)
Railway Board.